


Fig. 1
(PRIOR ART)



18

14

Fig. 2
(PRIOR ART)




Fig. 3
(PRIOR ART)




Fig. 4
(PRIOR ART)




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 15

PIPE JOINT
FEB 12 2003
ANALYSIS TRANSMISSION




Fig. 12




Fig. 13




Fig. 14




Fig. 16




Fig. 17





Fig. 18






Fig. 20




Fig. 21




Fig. 22